

Conventional and advanced mechanical manufacturing techniques (TFCA)

PROGRAM

Part I

1. Introduction
2. Foundry
3. Shaping by plastic deformation
4. Forming of flat products
5. Machining

Part II

1. electro-erosion
2. Sintering.
3. Photochemical machining.
4. Laser machining.
5. Explosion forming,
6. Electro-hydraulic forming.
7. Electromagnetic forming.